

The Institute of International Container Lessors



18 January 2024

IICL – Refrigerated Container Technical Bulletin – RTB 011 Review of Repair Limitations of Locking Bars of Refrigerated Containers.

IICL revised the repair limitations on door locking bars of refrigerated containers. RTB 011 is now available to view or download. The new RTB was issued under the supervision of our Technical Committee.

Here is the link to the new RTB:

https://www.iicl.org/iiclforms/assets/File/public/bulletins/RTB_011_Reefer_Repair_Door_Locking_Bars-January-2024.pdf

Contact technical@iicl.org if you have any questions.

Institute of International Container Lessors (IICL)
Tel: (202) 223-9800 - Website: www.iicl.org - Email: info@iicl.org

IICL | 4315 50th Street NW, Suite 100 - 7250, Washington, DC 20016

[Unsubscribe](mailto:info@iicl.org) | lqoncalves@iicl.org

[Update Profile](#) | [Constant Contact Data Notice](#)

Sent by info@iicl.org powered by

